


Verification



Design verification completed - Today - Not OK


Requirement name	Planned date	ID no	DV test report no	Legal Req	Test performer
Flammability	1135.7	3.1.1	727272		YTT
Head impact test	1139.4	5.13.9.3	112233		GTT

Design verification completed - Today - Not Planned

Requirement name	Planned date	ID no	DV test report no	Legal Req	Test performer
Heat resistance short term		5.3.3			GTT
Impact resistance at low temperature		7.3.3		YES	GTT

Design verification completed - Planned later then DV Gate W1140.5


Requirement name	Planned date	ID no	DV test report no	Legal Req	Test performer
Service lifetime	1143.5	6.6.1		YES	YTT



DV test report available - Not Planned

Requirement name	Planned date	ID no	DV test report no	Legal Req	Test performer
Heat resistance short term		5.3.3			GTT
Impact resistance at low temperature		7.3.3		YES	GTT
Flammability		3.1.1			YTT
Head impact test		5.13.9.3			GTT

Verification




Product verification - Planned later then PV Gate W1239.7

Requirement name	Planned date	ID no	DV test report no	Legal Req	Test performer
Flammability	1245.5	3.1.1			YTT

Product verification - Not Planned

Requirement name	Planned date	ID no	DV test report no	Legal Req	Test performer
Impact resistance at low temperature		7.3.3		YES	GTT
Head impact test		5.13.9.3			GTT



PV test report available - Not Planned

Requirement name	Planned date	ID no	DV test report no	Legal Req	Test performer
Impact resistance at low temperature		7.3.3		YES	GTT
Flammability		3.1.1			YTT
Head impact test		5.13.9.3			GTT